

December 13, 2014

Roads Water and Sewer Report

**Roads:** Various potholes were filled and compacted, other areas (Floriston Way down to the field) need to be addressed.

**Water:** Water samples were tested and recorded as required. The work to reconfigure the plumbing on the small water tank to use it as a settling and air removal system has been done. After a pump is specified and installed we will be able to bring the tank into the system and determine whether this will control the turbidity and air problems we have been experiencing. Samples have been tested as required. The boil order remains in effect.

**Sewer:** Samples were taken and submitted for testing as required. No issues were reported. Liberty energy needed to install a new power pole for the community and the best location was near our leach field. At this time we see no evidence of impact but it became clear that we need to:

- (A) identify that area on a permanent map
- (B) provide a means of restricting access
- (C) Install a sign to alert outside agencies that it is a sensitive area and restricted

Power meters were read and recorded as required.

Antifreeze was added to the toilet bowl in the schoolhouse to prevent freezing.

Power meters were read and recorded.

Submitted by Chuck Grooms,  
RWS FPOA