Road, Water and Sewer Report 11-7-17

other valves are operable. Seven service valves are pre-2000 and not current. was inoperable. Efforts will continue to break it free. The hydrant remains in service. All importance of keeping the valve boxes exposed. One 6" valve servicing a fire hydrant vaults had been buried by actions of the homeowner. They will be notified of the Inspection of the water main and service valves has been completed. Three service

canceled due to conditions requested by Jim Mawhar prior to his required approval. Work on removing the mud slide from behind the water tanks was delayed and then

portion of the wall pending the approval of Jim Mawhar. of the protective barrier buried. An urgent effort will be made to reinforce the chain link Our tank is presently subject to impact and damage from rocks with the concrete portion

problems which were corrected. continue as the weather permits. All 13 manholes were inspected with only minor Approximately 76% of the brush removal from the roads has been completed. Work will

Dennis Jamason RWS Commissioner