

Road. Water. Sewer Report 1/9/18

We have a new contractor responsible for plowing the county maintained portion of Floriston Way. A review of the current contract indicates the county changed the action level from 2" to 4" of snow accumulation. This creates hazardous conditions on the county road. In addition, the county fails to inspect the road during storms to assure contract performance. With no accountability, a flat rate contract is ineffective.

Town road maintenance will continue, weather permitting.

Dennnis Jamason